

## Kleenmaid RHSOG60 & RHSOG90 Rangehood Clip Control Problem

Issue: The rangehood does not start when pulling out the slider as supposed to.

Fix: Please watch the video at the below link to learn how to fix this issue.

[https://www.dropbox.com/s/6vod5f4rn8f7zru/RHSOG60%20RHSOG90%20Microswitch%20Repair%20Method%2020170320%20\(CAM01079\).mp4?dl=0](https://www.dropbox.com/s/6vod5f4rn8f7zru/RHSOG60%20RHSOG90%20Microswitch%20Repair%20Method%2020170320%20(CAM01079).mp4?dl=0)

For any questions regarding this, please do not hesitate to contact Kleenmaid.

