

Replacing the electronic vitiator and control panel on the RHSC90

9 March 2017

Parts:

Old part no: ECB0054046 electronic vitiator

New Part no: ECB0112539 electronic vitiator


Old part no: AGC0020123 complete control panel

Part no: AGC011257 complete control panel

Due to a change in design to how the wiring connecting the electronic vitiator and control panel connects, when installing the new parts, the connection direction changes.

Before replacement

The plug connects at the red CN5 part of the electronic vitiator with the wire connected to the control panel running away from the electronic vitiator.



When replacing

Reverse the plug direction. So, the plug connects at the red CN5 part of the electronic vitiator with the wire connected to the control panel running over from the electronic vitiator.

